

PFE HOSE



WHAT THEY DO

Connect the PFE sensor to the exhaust pipe. These are high temperature, silicone hoses.

FAILURE SYMPTOMS


Pinging, overheating, loss of power, MIL light on.

MAINTENANCE / SERVICE

Check hose to sensor for leaks, cracks or clogging when EGR system problems occur.

LOCATION

From exhaust pipe to PFE sensor.



May need to be cut to fit.

YEAR	ENGINE	MODEL		OE #	PART #
------	--------	-------	--	------	--------

FORD

4 cyl.

1995-1991	1.9L (J) 116"	Escort (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1990-1986	1.9L (J,9) 116"	Escort (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1994-1992	2.3L (X) 140"	Tempo (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1992-1988	2.3L (S,X) 140"	Tempo (Exc.FFV, w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1991-1986	2.5L (D,N) 153"	Taurus (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*

6 cyl.

1995	3.0L (1) 183"	Taurus (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1995-1992	3.0L (U) 183"	Tempo (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1995-1986	3.0L (U) 183"	Taurus (Exc.FFV,SHO, w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1992-1990	3.0L (U) 183"	Probe (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1992-1989	3.0L (U) 183"	Taurus SHO (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1994-1993	3.2L (N) 195"	Taurus SHO (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899
1995-1988	3.8L (R) 232"	Mustang, Taurus, Thunderbird (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1994-1988	3.8L (4) 232"	Taurus (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1993-1988	3.8L (4) 232"	Thunderbird (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*

8 cyl.

1994-1992	4.6L (W) 281"	Crown Victoria (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
-----------	---------------	-------------------------------	------------	-------------	--------

A complete cross reference from O.E.M. part numbers to Tomco Inc. part numbers begin on page 296.

PRESSURE FEEDBACK EGR HOSE

YEAR	ENGINE	MODEL		OE #	PART #
------	--------	-------	--	------	--------

FORD TRUCK

6 cyl.

1992-1991	2.9L (T) 177"	Ranger (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1990-1986	2.9L (T) 177"	Bronco II, Ranger (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1994-1991	3.0L (U) 183"	Ranger (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1994-1993	4.0L (X) 241"	Aerostar, Explorer, Ranger (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*

LINCOLN

6 cyl.

1993-1988	3.8L (4) 232"	Continental (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
-----------	---------------	----------------------------	------------	-------------	--------

MERCURY

4 cyl.

1995-1991	1.9L (J) 116"	Tracer (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1987-1986	1.9L (J) 116"	Lynx (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1994-1992	2.3L (X) 140"	Topaz (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1992-1988	2.3L (S,X) 140"	Topaz (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*

6 cyl.

1995-1988	3.0L (U) 183"	Sable (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1994-1992	3.0L (U) 183"	Topaz (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1995-1988	3.8L (R) 232"	Cougar, Sable (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1995-1988	3.8L (4) 232"	Sable (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
1995-1988	3.8L (4) 232"	Cougar (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*

8 cyl.

1994-1992	4.6L (W) 281"	Cougar, Grand Marquis (w/PFE Sensor)	Cut to Fit	E83Z-9P761B	10899*
-----------	---------------	--------------------------------------	------------	-------------	--------

OEM INTERCHANGE

NUMERICAL LIST

OEM#	PART#	PART#	APPLICATION & YEAR	FIG#
	FORD			
E83Z-9P761B	10899	10899*	FORD 86-95, F TRK 86-94, LINC 88-93, MERC 86-95	1



FIG. 1

* New in this Catalog